

The Tuning Works


Cylinder Reconditioning Service

From **£115** + VAT

Why are we more expensive than some others? TTW uses Apticoat Ceramic 2000 which is normally £176 per cylinder inc vat. Due to TTW popularity a better rate was negotiated with Aptec for TTW.

Below you can see what to expect from TTW. Here is a cylinder for one of our Australian customers. The cylinders required new water spigots, oil valves and studs. The Power-Valve bush was also removed and refitted.

The cylinders were honed to match the supplied pistons.



Once work is completed the customer is contacted for payment and the cylinders sent to anywhere in the world.

A comprehensive advice sheet is included to ensure you obtain the best results from your cylinders during engine break in.

Please call +44(0)1529 30 59 59 or
email sales@thetuningworks.com for further info

£115 is for a basic re-plate – extra charges may apply for removal and refitting of seized parts.